

PRACTICAL FIELD CHECKLIST

Use this list to keep your crew aligned and your lifts compliant—download, print, and hang this practical field checklist where everyone can see it.

**FOLLOWING OSHA AND ASME STANDARDS IS CRITICAL FOR
MAINTAINING SAFETY AND COMPLIANCE.**

✓ **TAGS & MARKINGS:**

Confirm every sling, device, or hardware piece shows legible ID and capacity before use.

✓ **ANGLES & LOAD PATH:**

Calculate sling leg tension for the lift angle; re-rig if angles are too shallow.

✓ **EDGE PROTECTION:**

Pad sharp edges or corners with material strong and thick enough to prevent damage.

✓ **HOOK LATCHES:**

Use them unless doing so introduces a greater hazard; never rely on the latch to support the load.

✓ **REMOVE-FROM-SERVICE TRIGGERS:**

Follow specific criteria by sling type (e.g., broken wires, deformation, tag missing).

✓ **DOCUMENTATION:**

Keep periodic inspection records for slings and below-the-hook devices; record proof-tests for custom devices.

✓ **QUALIFIED PEOPLE:**

Use qualified riggers and signal persons for crane work under Subpart CC.

